

Mine Name: Morton Salt - Grantsville

Inspector(s): Leslie Heppler

Operator Name: Morton International, Inc.

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R STYLER Executive Director JOHN R BAZA
Division I for

Inspection Report Minerals Regulatory Program

Date: June 1, 2009

4

Permit Number: M0450037

Inspection Date: 05/26/2009

Time: 11:00 am

Other Participants: Brett Gregory & Vicky Dyson		Mine Status: Active		
	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds	\boxtimes	\boxtimes	
2.	Public Safety (shafts, adits, trash, signs, highwalls)	\boxtimes	\boxtimes	
3.	Protection of Drainages / Erosion Control	\boxtimes	\boxtimes	
4_	Deleterious Material		\boxtimes	
5	Roads (maintenance, surfacing, dust control, safety)	\boxtimes	\boxtimes	
6	Concurrent Reclamation			
7.	Backfilling Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8.	Water Impoundments	\boxtimes	\boxtimes	
9.	Soils			
10.	Re-vegetation			
11.	Air Quality			

Bond Amount: \$2,129,975 **Bond Renewal Date** 03/22/2012 **Permit fee**: \$1000 due - invoice sent out 06/20/2009

Purpose of Inspection: Routine Annual Inspection, last inspection date 10/26/2006

<u>Inspection Summary</u>: The ponds were inspected on this inspection, next year the process facilities will be inspected. The ponds, canals, dikes, ditches and roads were all maintained in good shape, no erosion problems or deleterious material or trash was noted.

<u>Conclusions and Recommendations</u>: The mine was in good condition. No recommendations at this time.

Inspector's Signature

12. Other

LAH;vs

cc: Jim Huizingh

O:\M045-Tooele\M0450037-mortonSalt-grantsville\inspections\insp-05262009 doc

Inspection Date: 05/26/2009 Page 2 of 2 M/045/0037







